

**REQUEST FOR PROPOSAL PS- #1084**  
**Capacity Assessment of the State Water Project Coastal Branch**

**Addendum #2: Answers to Questions Received**

Q1: Does CCWA have any record of the interior condition of the pipes, either through video inspection or flow analysis?

A1: CCWA conducts annual internal pipeline inspections of selected sections of the pipeline. The internal inspections involve full dewatering of the pipeline section to be inspected. The inspection then proceeds with staff entering the pipeline and inspecting the interior conditions of the pipe. Any aberrant conditions of the mortar lining are noted and photographed. Areas in need of repair are immediately repaired during the annual inspection event. When applicable, the pipeline inspection includes measuring pipe diameter to monitor for excessive deflections. In general, the condition of the interior of the pipeline can be characterized as excellent. Also, to ensure that the interior condition is maintained in good condition, the Treatment Plant conditions the water to ensure that an aggressive index of 12.0 or greater is maintained along the full length of the pipeline.

Inspection records will be made available for review to the successful proposer.