
Appendix D

Baseflow Habitat Evaluation



Figure D-1. Lopez Dam release of 3 cfs. At the Lagoon on 2/3/21 (a), 22nd Street Bridge on 2/3/21 (b), and City of Arroyo Grande on 2/1/21 (c-d). No flow measurements available.



Figure D-2. Lopez Dam release of 3 cfs at Cecchetti Road on 1/29/21. No flow measurements available.



Figure D-3. Lopez Dam release of 5 cfs at the 22nd St. Bridge on 7/21/21 at 0 cfs (a), Upstream of the lagoon on 7/21/21, flow measured at 1.1 cfs (b), and City of Arroyo Grande on 7/22/21, flow measured at 1.9 cfs (c-d).



Figure D-4. Lopez Dam release of 5 cfs at Cecchetti Road on 7/21/21, flow measured at 2.7 cfs (a-b), and at Talley Farms Road on 7/22/21, flow measured at 3.5 cfs (c-d).



Figure D-5. Lopez Dam release of 7 cfs upstream of the lagoon on 9/6/21 at 0 cfs (a), upstream of the lagoon on 9/6/21, flow measured at 2.2 cfs (b), and City of Arroyo Grande on 9/6/21, flow measured at 3.9 cfs (c-d).



Figure D-6. Lopez Dam release of 7 cfs at Cecchetti Road on 9/6/21, flow measured at 4.5 cfs (a), and at Talley Farms Road on 9/6/21, flow measured at 5.2 cfs (b-c).



Figure D-7. Lopez Dam release of 8 cfs upstream of the lagoon on 3/3/25 (a-b) and City of Arroyo Grande on 3/5/25 (c-d). No flow measurements available.



Figure D-8. Lopez Dam release of 8 cfs at Cecchetti Road on 3/27/25 (a-b). No flow measurements available.