CAYUCOS BEACH MUTUAL WATER COMPANY 2023 Water Quality Report

P.O. Box 315, 425 S. Ocean Avenue, Cayucos, CA 93430 (805) 995-3766



PUBLISHED MAY 2024

To our customers: Cayucos Beach Mutual Water Company is pleased to present this annual report describing the quality of your drinking water.

Este informe contiene informacíon muy importante sobre su agua dé beber. Tradúzcalo ó hable con alguien que lo entienda bien.

What is the source of my drinking water?

Your water comes from Whale Rock Reservoir and a groundwater well located in Cayucos on the east side of Highway One. Whale Rock Reservoir has a total capacity of 38,967 acre-feet and is managed by the Whale Rock Commission (City of San Luis Obispo, California Men's Colony, and Cal Poly University). No swimming or other body contact sports are allowed in the reservoir in order to minimize viral contamination from human contact. Water from the reservoir is piped downstream to the Cayucos Water Treatment Plant (WTP) where it is filtered with a percentage of water passing through two granular activated carbon filters. Water is chlorinated prior to distribution. Treated water is distributed to the three water purveyors in Cayucos: Cayucos Beach Mutual Water Company (CBMWC), Morro Rock Mutual Water Company (MRMWC) and the County of San Luis Obispo County Service Area 10A (CSA 10A). These three agencies have a combined entitlement of 582 acre-feet per year of Whale Rock Reservoir water plus access to a small amount of groundwater. The Whale Rock watershed is approximately 20.3 square miles in size and is susceptible to the following contamination: wastewater, animal grazing, recreational activities, unauthorized activities, use of pesticides/ herbicides, geological formations and hazardous materials spills. The watershed is well managed and these potential sources of contamination are minimized.

Sanitary surveys of the watersheds above and below Whale Rock Reservoir were updated in 2021. The source assessments of selected Cayucos Area Water Organization (CAWO) wells were also updated in 2021. The surveys and assessments were conducted to locate potential sources of contamination and evaluate the ability of the water treatment plant and wells to handle the contamination. The updated studies included a review of water system information, meetings with water system staff, and field reconnaissance. No significant changes were noted in the watersheds. The source assessments continue to conclude that the wells were most vulnerable to the following activities for which no associated contaminant has been detected in the water supply: Sewer collection system, low-density septic systems, agricultural drainage and an agricultural well.

A copy of the complete assessment is available at: California State Water Resources Control Board, Division of Drinking Water, 1180 Eugenia Place, Suite 200, Carpinteria, California 93013

Cayucos Beach Mutual Water Company 425 South Ocean Avenue, Cayucos CA 93430

County of San Luis Obispo, Department of Public Works, County Government Center, Room 207, San Luis Obispo, CA 93408.

You may also request a summary of the source assessment report by contacting: Faith Zenker, Water Quality Manager, County of San Luis Obispo (805)781-1576.



Where is the water tested?

Water analyses are performed by the San Luis Obispo County Water Quality Laboratory or contracted to another certified laboratory. The county lab is certified by the CSWRCB-DDW as an environmental testing laboratory for bacteriological and chemical analyses. Federal and State requirements dictate that all regulatory analyses be performed by certified labs following approved procedures. Faith Zenker, Water Quality Manager, can be reached at (805) 781-1576.

The water purveyors each monitor their water wells on a regular basis for regulated and unregulated chemicals and evaluate the findings relative to the California Drinking Water Primary and Secondary Maximum Contaminant Level (MCL) Standards. These monitoring results are then submitted to the California State Water Resources, Control Board, Division of Drinking Water.

Who operates the distribution system?

Ray Bruno is D3 certified by the California State Water Resources, Control Board, Division of Drinking Water (CSWRCB-DDW). Dan Musolff is D1 certified by the California State Water Resources, Control Board, Division of Drinking Water. Ron Boyte, our contract employee who consults as needed, is D2 certified. Both Ron and Ray are knowledgeable professionals who have many years of experience. Dan is working hard to build up his knowledge and is learning a lot from them.

Daily and weekly inspections of the well, tanks and distribution system are done to ensure a safe and reliable water supply. The CSWRCB-DDW routinely inspect the facilities, operating procedures and water quality monitoring records to verify compliance with state and federal regulatory requirements.

Where can the community participate in decisions regarding water quality or other water issues?

The Cayucos Area Water Organization (CAWO) meets the first Monday of every other month at 425 S. Ocean Avenue, Cayucos, CA 93430 at 1:30 p.m.

(January, March, May, July, September and November) The Cayucos Beach Mutual Water Company Board of Directors meets the first Tuesday of the month at 10:00 a.m. at 425 S. Ocean Avenue. The Annual Shareholders meeting is held on the first Tuesday of May at 10:00 a.m. following the regular monthly meeting at 425 S. Ocean Avenue, Cayucos CA 93430.

Sources of Drinking Water

The sources of drinking water (both tap water and bottled water) include rivers, lakes, streams, ponds, reservoirs, springs, and wells. As water travels over the surface of the land or through the ground, it dissolves naturally occurring minerals and, in some cases, radioactive material, and can pick up substances resulting from the presence of animals or from human activity.

Contaminants that may be present in source water include:

- Microbial contaminants, such as viruses and bacteria, which may come from sewage treatment plants, septic systems, agricultural livestock operations, and wildlife.
- Inorganic contaminants, such as salts and metals, which can be naturally occurring or result from urban storm water runoff, industrial or domestic wastewater discharges, oil and gas production, mining, or farming.
- Pesticides and herbicides, which may come from a variety of sources such as agriculture, urban storm water runoff, and residential uses.
- Organic chemical contaminants, including synthetic and volatile organic chemicals, which are by-products of industrial processes and petroleum production, and can also come from gas stations, urban storm water runoff, and septic systems.
- Radioactive contaminants which can be naturally occurring or be the result of oil and gas production and mining activities.
 In order to ensure that tap water is safe to drink, the United States Environmental Protection Agency (USEPA) and the California State Water Resources Control Board, Division of Drinking Water (CSWRCB-DDW) prescribe regulations which limit the amount of certain contaminants in water provided by public water systems. CSWRCB-DDW regulations also establish limits for contaminants in bottled water which must provide the same protection for public health.

USEPA Office of Ground Water and Drinking Water www.epa.gov/safewater/
California State Water Resources Control Board,
Division of Drinking Water
www.swrcb.ca.gov/drinking_water/programs/
index.shtml
San Luis Obispo County Public Works Department
www.slocountywater.org

All drinking water, including bottled water, may reasonably be expected to contain at least small amounts of some contaminants. The presence of contaminants does not necessarily indicate that water poses a health risk. More information about contaminants and potential health effects can be obtained by calling the US EPA's Safe Drinking Water Hotline, 1-800-426-4791.

Some people may be more vulnerable to contaminants in drinking water than the general population.

Immune-compromised persons such as persons with cancer undergoing chemotherapy, persons who have undergone organ transplants, people with HIV/AIDS or other immune system disorders, some elderly, and infants can be particularly at risk from infections. These people should seek advice about drinking water from their health care providers. The USEPA and Centers for Disease Control (CDC) guidelines on appropriate means to lessen the risk of infection by Cryptosporidium and other microbial contaminants are available from the Safe Drinking Water Hotline, 1-800-426-4791.

Additionally, the EPA Office of Ground Water and Drinking Water maintains a website with useful information on drinking water. The address is www.epa.gov/safewater/. Information can also be obtained by accessing the American Water Works Association's website at www.awwa.org, the CSWRCB-DDW website at http://www.swrcb.ca.gov/drinking_water/programs/index.shtml, or by calling Faith Zenker, San Luis Obispo County Water Quality Manager, at (805) 781-1576.

If present, elevated levels of lead can cause serious health problems, especially for pregnant women and young children. Lead in drinking water is primarily from materials and components associated with service lines and home plumbing.

The water company is responsible for providing high quality drinking water, but cannot control the variety of materials used in plumbing components. When your water has been sitting for several hours, you can minimize the potential for lead exposure by flushing your tap for 30 seconds to 2 minutes before using water for drinking or cooking. If you are concerned about lead in your water, you may wish to have it tested. Information on lead in drinking water, testing methods, and steps you can take to minimize exposure is available from the Safe Drinking Water Hotline 1-800-426-4791 or at http://www.epa.gov/safewater/lead.





- 1. Toilets should not be running more than a few seconds after a flush. If it continues to run beyond that, several components may be bad. A running toilet indicates that there is a leak somewhere between the tank and the bowl.
- 2. Do not allow the application of potable water to outdoor landscapes runoff such that water flows onto adjacent property, non-irrigated areas, private and public walkways, roadways, parking lots, or structures.
- 3. The use of a hose that dispenses potable water to wash a vehicle, should have a shut off nozzle or device attached to it that causes it to cease dispensing water immediately when not in use.
- 4. Sweep walkways, driveways, patios and decks do not wash with a hose.
- 5. Don't let the water run turn water off when brushing teeth or shaving and shower quickly.

Throughout 2023, hundreds of water samples were collected in order to determine the presence or absence of any biological, radioactive, inorganic or organic contaminants in your drinking water. On the next page are the Tables that list all of the drinking water contaminants that were detected from January 2023 through December 2023, unless otherwise noted. The presence of these contaminants in water does not necessarily indicate that the water poses a health risk. The California State Water Resources Control Board, Division of Drinking Water does not require us to monitor for certain contaminants every year because the concentrations of these are not expected to vary significantly from year to year. Some of this data may be more than one year old, but is still representative of the water quality. In these cases, the most recent sample data are included along with the year in which the sample was collected. Below is a list of Key Terms used in this report.

KEY TERMS

AL (Action Level, Regulatory): The concentration of a contaminant that, if exceeded, triggers treatment or other requirement which a water system must follow.

CDPH: California Department of Public Health **CFU/mL:** Colony Forming Units per milliliter

CU: color units

DBP: Disinfection By-Product

LRAA (Locational Running Annual Average): An arithmetic average is computed quarterly for each site and compliance is based on the running average of quarters,

MCL (Maximum Contaminant Level): The highest level of a contaminant that is allowed in drinking water. Primary MCLs are set as close to the PHGs (or MCLGs) as is economically and technologically feasible.

MCLG (Maximum Contaminant Level Goal): The level of a contaminant in drinking water below which there is no known or expected risk to health.

MCLGs are set by the United States Environmental Protection Agency.

MRDL (Maximum Residual Disinfectant Level): The level of a disinfectant added for water treatment that may not be exceeded at the consumer's tap.

MRDLG (Maximum Residual Disinfectant Level Goal): The level of a disinfectant added for water treatment below which there is no known or expected risk to health. MRDLGs are set by the U.S. Environmental Protection Agency.

ND (Not Detected): Contaminant is not detectable at testing limit. NA: Not Applicable NL (Notification): The concentration of a contaminate that, if exceeded triggers treatment or other requirement which a water system must follow. NS: No Standard

NTU: Nephelometric Turbidity Unit

PDWS (Primary Drinking Water Standard): MCLs and MRDLs for contaminants that affect health along with their monitoring and reporting requirements, and water treatment requirements.

PHG (Public Health Goal): The level of a contaminant in drinking water below which there is no known or expected risk to health. PHGs are set by the California Environmental Protection Agency.

pCi/L: (picoCuries per liter) a measure of radioactivity.

ppm: parts per million, or milligrams per liter (mg/L)

ppb: parts per billion, or micrograms per liter (µg/L)

RAA (Running Annual Average): Average data for last four quarters.

SDWS (Secondary Drinking Water Standard): MCLs for contaminants that affect taste, odor, or appearance of the drinking water. Contaminants with

SDWSs do not affect health at the MCL levels.

TON: Threshold Odor Number

TT (Treatment Technique): A required process intended to reduce the level of a contaminant in drinking water.

μS/cm (microSiemens per centimeter): A measure of electrical conductance.

(1 S = 1 ohm-1)



CAYUCOS BEACH MUTUAL WATER COMPANY 2023 DATA SUMMARY TABLE	Delivered Water is a combination of water from two sources, CAWO Well and Whale Rock Reservoir. In 2023, CAWO Well provided less than 1.00% and Whale Rock Reservoir (Treated) provided more than 99.00% of the delivered for most part of the part of parts of the part of th
--	--

				CAYUCOS BE	ACH MUTUA	WATER CON	APANY 2023 E	CAYUCOS BEACH MUTUAL WATER COMPANY 2023 DATA SUMMARY TABLE	Y TABLE	
Delivered Water is a water delivered. Fo	r question	tion of water fron is about this data	n two sources, 1, contact Cayud	CAWO Well and W	hale Rock Reser Water Company	voir. In 2023, CAW (805) 995-3766 or	VO Well provided San Luis Obispo	less than 1.00% an County Water Qual	d Whale Rock Re lity Laboratory (8	Delivered Water is a combination of water from two sources, CAWO Well and Whale Rock Reservoir. In 2023, CAWO Well provided less than 1.00% and Whale Rock Reservoir (Treated) provided more than 99.00% of the water delivered. For questions about this data, contact Cayucos Beach Mutual Water Company (805) 995-3766 or San Luis Obispo County Water Quality Laboratory (805) 781-1576.
STATE OF STATE OF					DETECTION OF	DETECTION OF PRIMARY DRINKING WATER STANDARDS	KING WATER S	TANDARDS	1000年の日本の日本の日本の日本の日本の日本の日本の日本の日本の日本の日本の日本の日本の	
CONTAMINANT	UNITS	YEAR SAMPLED	1 00	AVFRAGE	TABLE: 1	TABLE: 1 MICROBIOLOGICAL CONTAMINANTS	CAL CONTAMIN	ANTS		POTENTIAL SOLIBCE OF CONTAMINATION
Total Coliform	Present or			Ab	Absent			Absent		Naturally present in the environment
E. coli	Present or	2023		Abs	Absent			Absent		Himan and animal fecal waste
Heterotrophic Plate Count	CFU/mL	2023		Z	Q			ND -25		Naturally present in the environment
					ABLE 2: LEAD	TABLE 2: LEAD AND COPPER FROM CONSUMER'S HOMES	ROM CONSUME	R'S HOMES		ואמנעומוון או חוס פוואווסוווופות
CONTAMINANT	UNITS	YEAR SAMPLED	NUMBER OF SAMPLES	90 th PE	90th PERCENTILE COLLECTED	D NUMBER OF SITES EXCEEDING	S EXCEEDING ACTION	ION PUBLIC HEALTH GOAL	H GOAL AVERAGE	POTENTIAL SOURCE OF CONTAMINATION
Copper	qdd	2022	10	2	100.0	0		300	ON.	
Lead	qdd	2022	10		3.	0	15	5 0.2	Q	deposits, recoming from most preservatives in Internal corrosion of household plumbing;erosion of natural deposits.
STOREST STORES	BICKES SOM	Section My Concess	TABLE 3: DISI	INFECTION BYPI	RODUCTS, DISI	NFECTANT RES	IDUALS, and DI	SINFECTION BYP	RODUCT PREC	URSORS
CONTAMINANT	STINO			YEAR	HIGHEST RUNNINA ANNUAL AVERAGE	S RANGE DETECTE	ED MCL			YEAR HIGHEST RUNNING RANGE DETECTED MCL. SAMPLED ANNUAL AVERAGE IMPORTANTIAL SOURCE OF CONTAMINATION
Total Trihalomethane	qdd			2023	36.3	19.1-55		RAA = 80		Byproduct of drinking water chlorination
Haloacetic Acids	qdd			2023	9.6	3.9-14.5		RAA = 60		Byproduct of drinking water chlorination
Chlorine Residuals	шфф			2023	1.05 (Annual Average)	0.86-1.40		[4.0 as CI2]		Drinking water disinfectant added for treatment
						TABLE 4: RADIOACTIVE CONTAMINANTS	'E CONTAMINAN	ITS		
CONTAMINANT	UNITS	YEAR SAMPLED	Treated V	Water Average Detected		Where Sampled	MCL		MCLG	POTENTIAL SOURCE OF CONTAMINATION
Gross Alpha Particle Activity	pci/L	2023		3.4	Sou	Source Water	15		N/A	Erosion of natural deposits
		SOLD SOLD SOLD SOLD SOLD SOLD SOLD SOLD			TABLI	TABLE 5: INORGANIC CONTAMINANTS	CONTAMINAN	S	STANDARD CONTRACTOR	
CONTAMINANT	UNITS	YEAR SAMPLED	4	Average Detected		Where	MCL		PHG (MCLG)	POTENTIAL SOURCE OF CONTAMINATION
Arsenic	qdd	2023		2.1	Trea	Treated Water	10		0.004	Erosion of natural deposits; runott from orchards; glass and electronics production wastes.
Fluoride	mdd	2023		0.29	Trea	Treated Water	а		-	Erosion of natural deposits; water additive that promotes strong teeth; Discharge from fertilizer.
Nitrates as NO ₃ (ppm)	mdd	arcc		0.34	Sou	Source Water	10		10	Runoff and leaching from fertilizer use; leaching from septic tanks and
	Section Section	2010	TA	RIFE-DETECT	ON OF CONTAI	HTIM STNANIN	SECONDARY	DRINKING WATER	STANDARD	sewage, erosion of fatural deposit.
CONTAMINANT	UNITS	YEAR SAMPLED	4	Average Detected (Range)	, i	Where	MCL	Average Defected MCL MCL PHG (MCLG) Range (Range)	PHG (MCLG)	POTENTIAL SOURCE OF CONTAMINATION
Aluminum	шdd	2023		61 ND-110	Trea	Treated Water	200		N/A	Erosion of natural deposits, residue from surface water treatment process
Color	3	2023		ND ND-2.0	Ď	Delivered	7		Ϋ́Z	Naturally occurring organic materials
Odor - Threshold	NOT	2023		ND ND-1.4	ă	elivered	m		Α'N	Naturally occurring organic materials
Specific Conductance	пS/ст	2023		640 640	Trea	ted Water	1600	640 Treated Water 1600 N/A Su	N/A	Substances that form ions when in water;seawater influence
Sulfate	шdd	2023		80	Trea	rted Water	500		N/A	Runoff/leaching from natural deposits
Total Dissolved Solids	mdd	2023		390	Trea	ted Water	1000		Ϋ́Α	Runoff/leaching from natural deposits
Turbidity	ΣŅ	2023		0.10	Ď	elivered	v.		A/Z	Surface Water Runoff
	Statement of the statem			TABLE 7: DET	ECTION OF CO	NTAMINANTS W	ITHOUT A DRIN	KING WATER ST	NDARD	
CONTAMINANT	STINO	YEAR SAMPLED	₹	Average Detected (Range)	ď	Where	MCL		PHG (MCLG)	POTENTIAL SOURCE OF CONTAMINATION
Alkalinity as CaCO3	шdd	2023		197	Trea	ted Water	SZ		Ϋ́Z	Runoff/leaching from natural deposits:seawater influence
Calcium	Шdd	2023		50	Trea	ted Water	SN.		N/A	Runoff/leaching from natural deposits;seawater influence
Hardness as CaCO3	шdd	2023		290 290	Trea	ted Water	NS		N/A	Generally found in ground and surface water
Magnesium	шdd	2023		04 46	Trea	ted Water	SN		N/A	Runoff/leaching from natural deposits;seawater influence
Sodium	шdd	2023		36 35	Trea	ted Water	SN		N/A	Runoff/leaching from natural deposits:seawater influence
Hd		2021		8.06 7.5-8.5	Trea	Treated Water	SN		NA	Runoff/leaching from natural deposits;seawater influence