

San Luis Obispo County Regional Invasive Mussel Monitoring Program Monthly Summary Report for January 2024

Monitoring Site Inspections

Reservoir	Agencies	No. of sites	Number of sites inspected	Any confirmed positive?
Lopez Lake	SLO Co. PWD/SLO Co. Parks	3	3	No
Lopez Terminal	SLO Co. PWD	1	1	No
Salinas	SLO Co. PWD/SLO Co. Parks	3	3	No
Whale Rock	SLO Co. PWD/City of SLO	1	1	No
Nacimiento	SLO Co. PWD	3	3	No
Lake Cachuma	SB Co. Parks	5	4 ¹	No

General notes on monitoring site inspections

- A site inspection may include inspection of an artificial substrate and/or a surface survey (docks etc). At some sites a fairly extensive inspection is performed, at others it may be more limited.

For more information about invasive mussel monitoring at Lake Cachuma contact Rosey Bishop at rbishop@co.santa-barbara.ca.us or (805) 688-4515.

¹ Station compromised. Rope holding substrates snapped.

San Luis Obispo County Regional Invasive Mussel Monitoring Program Monthly Summary Report for February 2024

Monitoring Site Inspections

Reservoir	Agencies	No. of sites	Number of sites inspected	Any confirmed positive?
Lopez Lake	SLO Co. PWD/SLO Co. Parks	3	3	No
Lopez Terminal	SLO Co. PWD	1	1	No
Salinas	SLO Co. PWD/SLO Co. Parks	3	3	No
Whale Rock	SLO Co. PWD/City of SLO	1	1	No
Nacimiento	SLO Co. PWD	3	3	No
Lake Cachuma	SB Co. Parks	5	5	No

General notes on monitoring site inspections

- A site inspection may include inspection of an artificial substrate and/or a surface survey (docks etc). At some sites a fairly extensive inspection is performed, at others it may be more limited.

For more information about invasive mussel monitoring at Lake Cachuma contact Rosey Bishop at rbishop@co.santa-barbara.ca.us or (805) 688-4515.

San Luis Obispo County Regional Invasive Mussel Monitoring Program Monthly Summary Report for March 2024

Monitoring Site Inspections

Reservoir	Agencies	No. of sites	Number of sites inspected	Any confirmed positive?
Lopez Lake	SLO Co. PWD/SLO Co. Parks	3	0 ¹	--
Lopez Terminal	SLO Co. PWD	1	1	No
Salinas	SLO Co. PWD/SLO Co. Parks	3	3	No
Whale Rock	SLO Co. PWD/City of SLO	1	0 ²	--
Nacimiento	SLO Co. PWD	3	3	No
Lake Cachuma	SB Co. Parks	5	5	No

General notes on monitoring site inspections

- A site inspection may include inspection of an artificial substrate and/or a surface survey (docks etc). At some sites a fairly extensive inspection is performed, at others it may be more limited.

For more information about invasive mussel monitoring at Lake Cachuma contact Rosey Bishop at rbishop@co.santa-barbara.ca.us or (805) 688-4515.

¹ Short-staffed; no monitoring performed

² Inaccessible; station moved

San Luis Obispo County Regional Invasive Mussel Monitoring Program Monthly Summary Report for April 2024

Monitoring Site Inspections

Reservoir	Agencies	No. of sites	Number of sites inspected	Any confirmed positive?
Lopez Lake	SLO Co. PWD/SLO Co. Parks	3	3	No
Lopez Terminal	SLO Co. PWD	1	1	No
Salinas	SLO Co. PWD/SLO Co. Parks	3	3	No
Whale Rock	SLO Co. PWD/City of SLO	1	1	No
Nacimiento	SLO Co. PWD	3	3	No
Lake Cachuma	SB Co. Parks	5	5	No

General notes on monitoring site inspections

- A site inspection may include inspection of an artificial substrate and/or a surface survey (docks etc). At some sites a fairly extensive inspection is performed, at others it may be more limited.

For more information about invasive mussel monitoring at Lake Cachuma contact Rosey Bishop at rbishop@co.santa-barbara.ca.us or (805) 688-4515.