

SECTION 9. DESCRIPTION OF WORK

Stabilize and rebuild approximately 60 foot long segment of a 35 foot high creek bank along Rocky Creek, adjacent to Santa Rosa Creek Road, about 0.9 miles north of Highway 46 in Paso Robles, California, including clearing and grubbing, tree removal, excavation, grading, rock slope protection, geosynthetic reinforced emabankment, install willow root balls for rock slope protection, erosion control, hydroseeding, drainage pipe, asphalt pavement, metal beam guard rail, and roadside signs, and such other items or detail work not mentioned herein that are required by the Plans, the Standard Specifications and/or these Special Provisions shall be performed, constructed, furnished and/or installed.