# CSA 23 Water System Update April 2025

# **OPERATIONS**

- 1. System operations have been routine for the month of March.
- 2. The water status remains Normal.
- 3. Chlorine residuals average between 1.48 2.04 mg/l.
- 4. The static well depth for Well 3 is 13.8 feet.
- 5. The static well depth for Well 4 is 7.50 feet.
- 6. Responded to multiple Underground Service Alert (USA) location requests.

# **WATER SYSTEM PROJECTS**

Project	Description	Estimate	Phase
Replace Bolted Water Storage Tank	Replace tank to extend asset life 50 years.	\$1,750,000 This project will be funded through a grant from the American Rescue Plan Act (ARPA).	Construction contract in amount \$931,091 awarded to Crosno Construction and a Notice to Proceed has been issued for materials.  Construction is expected to start April 7 <sup>th.</sup>

# CSA 23 Zone A

Zone A will be established within the newly annexed area of CSA 23 to provide water service to Phase 1 (38 residential lots) of Tract 2586, with plans for future expansion as Phases II and III are developed. The creation of Zone A will define service responsibilities, establish equitable rates, and secure funding for reliable water service. Tentative Board Dates: April 29 – Resolution to Initiate Formation of Zone A and Introduction of Rate Ordinance; Public Hearing on June 17.

**BUDGET REPORT** 1. A budget summary is attached to this report.

Fund:

CSA 23 Water Monthly Report J. Cavazos Prepared by: Date of Prep: 3/5/2025 Report Period: 2/1/25-2/28/25

67% % of Yr Complete

COUNTY SERVICE AREA 23 WATER BUDGET STATUS REPORT					]		
Internal Orders & WOs (Operations and Maint)		Budget/Plan	Actual	% of Budget	Encumbered PO's	Available	
591R360142 CSA 23 NEW SERVICES	\$	<del>-</del>	2,178			(2,178)	
591R361003 CSA23- TR 2586 SMRMWC	\$	24,910	\$ 38,354	154.0%		(13,444)	
591R365135 CSA 23 WORK ORDERS		376,501	235,090	62.4%	-	141,411	
591R365150 CSA 23 GENERAL OPERATIONS		51,106	26,934	52.7%	-	24,172	[b] - actual
591R365181 VAC-TRON AIR 555, TRAILER MOUNTED			258			(258)	
591R365182 MINI HYDAULIC EXCAVATOR, CAT			2,764			(2,764)	
591R365210 CSA 23 UTILITIES		38,737	22,444	57.9%	-	16,293	
591R365310 CSA 23 WQ ANALYSES		52,085	19,602	37.6%	-	32,483	
591R365350 CSA 23 WQ OPER. SUPPORT		48,099	25,821	53.7%	-	22,278	
591R365410 CSA 23 STORMWATER ANNUAL INSPECTION			2,135		19,435.20	(21,570)	
591R365602 CSA 23 ACCTG and ADMIN		28,375	12,178	42.9%	-	16,197	
591R365502 CSA 23 Customer Accounts		12,742	11,077	86.9%	-	1,665	
591R365620 CSA 23 County Wide OverHead		11,112	12,283	110.5%	-	(1,171)	
591R360225 SCADA Efforts O&M		43,315		0.0%	-	43,315	
Total O&M	\$	686,982	\$ 411,118	59.8%	\$ 19,435	\$ 256,429	
Capital Projects		Budget	Actual		Encumbered PO's	Available	
300667 ARPA Replace Bolted Water Tank		1,472,794	36,058	0.0%	1,030,457	406,279	
Total Capital Projects	\$	1,472,794	\$ 36,058		\$ 1,030,457	\$ 406,279	
Loan Payments		Budget	Actual		Encumbered PO's	Available	
USDA Loan & Interest	\$	86,875	58,766	67.6%	-	28,109	
General Fund Loan & Interest		12,973	6,420	49.5%	-	6,553	
Total Loan Payments	\$	99,848	\$ 65,186	65.3%	\$ -	\$ 34,662	
GRAND TOTAL		Budget	Actual		Encumbered PO's	Available	
Grand Total	\$	2,259,624	\$ 512,362	22.7%	\$ 1,049,892	\$ 697,370	[a] - POs

3/27/2025

#### CSA 23: Encumbrances/PO's Detail:

			Remaining Encumbered			Remaining Not Encumbered	
<u>PO#</u>	<u>Vendor Name</u>	Line on PO	<u>Amount</u>	Internal Order	PO Description	Available Limit	Delivery Date
25012077	ADVANTAGE TECHNICAL SERVICES INC		-	591R365135	Tank Inspection & Repair	549	6/30/24
25016435	ADVANTAGE TECHNICAL SERVICES INC line 9		-	591R365135			
25016758	BATTERY SYSTEMS INC			591R365135	Batteries and Supplies	8,458	6/30/25
25008913	CANNON CORP			591R365135	Blanket PO Electronic Svcs-Santa Marg	7,113	6/30/24
25017522	CROSNO CONSTRUCTION		1,024,200.00	300667.08	Contract 300667 Bolted Water Tank	-	
25017708	DC INSPECTIONS			300667.08	Material Testing Tank	10,000	
25017698	GEOSOLUTIONS INC			300667.08	Material Testing Tank	10,000	
25014987	HACH CO			591R365135	NC-SD Equipment & Supplies	9,447	6/30/25
25017009	MILLER DRILLING CO			591R365135	Inspection, Labor & Replacement	10,000	
22020912	MILLER DRILLING CO		19,435.20	591R365410	Pump Replacement		
25016921	SOUZA			591R365135	CSA 23 Misc Parts and Labor	747	6/30/27
25016317	SURFACE PUMPS INC		-	591R365150	Maintenance Services as needed	8,645	6/30/26
25004470	VICTOR BACKHOE INC			591R365135	Installations-Santa Marg	33,893	6/30/24
25016180	XIO INC		-	591R365135	SCADA System Equipment for CSA 23	35,000	6/30/24
25016030	YEH & ASSOC INC		6,257.10	300667.01	CSA 23 Water Storage Tanks	_	2/1/27
			<u>1,049,892.30</u>	[a]	•	133,852	

# CSA 23: Work Order Actuals Detail for 591R365135 (above)

		<u>Actuals</u>	% of Total W
40234709	Routine Operations 23/24	2,550.00	
40234716	USA Locations 23/24	256.00	(
40234717	Weed Abatement 23/24	182.00	(
40234720	Customer Account 23/24	182.00	(
40238862	Well 3 Maintenance 23/24	298.00	(
40239474	Installing New Sample Station	2,221.00	(
40240174	Repair service leak at 22155 F	833.00	(
40240931	Common Area Efforts	41.00	(
40243295	Repair service leak 22155 F St	1,111.00	(
40243341	Service leak repair @ 9547 Encina	2,221.00	(
40243443	Service line repair - 22460 F	1,388.00	(
40246337	North County Standby Miles	3.00	(
40246339	Booster Sewer Repair - Blockag	570.00	(
40248531	Tank Communication Issue	1,372.00	(
40249771	Routine Operations 24/25	104,506,00	44
40249773	Building Maintenance 24/25	5,083.00	2
40249774	Meter Reading 24/25	7,282.00	(
40249775	USA Locations 24/25	4,353.00	
40249776	Weed Abatement 24/25	1,292.00	(
40249777	SCADA Support 24/25	5,077,00	
40249780	Well #3 Filter Backwash 24/25	2,099,00	(
40249782	Meter Replacement 24/25	1,673.00	(
40249839	Santa Margarita Generator	128.00	(
40250043	North County Standby Mileage	1,797.00	(
40250046	Shared System Maintenance	1,841.00	(
40250066	Budget Prep 24/25	1,916.00	(
40250297	Routine Water Sample 24/25	17,175.00	
40250505	High Turbidity Alarm at Well #4	639.00	(
40250696	CSA 23 Tank Communication Issue	2,105.00	(
40250765	Lead service line inventory 24-25	13,238.00	į
40250918	22835 El Camino Real Water Ser	617.00	(
40250936	Annual Generator Service-Onan	875.00	(
40251079	22909 El Camino Real Water Leak	3,807,00	
40251203	Late Notice Water Shut offs	298.00	(
40251299	I Street/Estrada Service Insta	1,467.00	(
40251361	Well #4 Low Chlorine Alarm.	2,068.00	(
40251365	Booster Station Well Repair	86.00	(
40251450	Install New 2" Flow Meter at W	566.00	(
40251768	Power outage call out Well 4	182.00	(
40251882	Gate entry camera installation	136,00	(
40251912	Water Shut Offs CSA23	1,446.00	(
40252025	CSA23 Distribution Maintenance	1.031.00	
40252335	Cycle flushing Well #3	1,539.00	
40252652	Low Chlorine nuisance alarm re	325.00	
40252981	Investigate High Chlorine leve	325.00	
40253643	Water Leak 22660 I St.	741.00	
40253896	Repair water leak @ 203 Escondido	700.00	

Charged to 591R360142 New Services ORD 40251591 22121 I St Santa Margarita	<u>2,177.68</u>
591R365210 CSA 23 Utilities	
ORD 40251012 Common Area Utilities FY 24/25	436.00
ORD 40240998 Office Admin Material & Cleani	20.08
ORD 40257336 Fix plugged septic line	41.00
Total	497.08
591R365410 CSA 23 STORMWATER ANNUAL INSPECTION	
ORD 40257480 Inspection of well #3	2,135.00
591R365602 ACCTG AND ADMIN	
ORD 40251416 Office Admin Materials & Clean	<u>116.00</u>

Total Work Orders		235,090	[b]
		11,521.81	
	ОН	474.93	
	Advantage Technical Services	1,710.00	
	Souza Construction	9,255.34	
Charged Directly to IO	Office Expense US Bank	81.54	
Total Work Orders		223,568.00	
-10200000	Tron banding gatter installation	1,713.00	
40258833	Well building gutter installation	1,719.00	
40257673	Well 4 tree trimming & limb re	3,572.00	
40257482	9720 Encina Customer leak	941.00	
40257461	Annual Generator Service-Onan	339.00	
40257372	Booster Station Monthly Fuel I	20.00	
40257341	Innertie -	443.00	
40257329	Call Out, Possible leak By Tanks	319.00	
40257329	Well #4 Flushing and Cycle Test.	1,926.00	
40256990	Valve Exercising and Hydrant M	1,446,00	
40256711	Santa Margarita Tank Daily CL2	601.00	
40256569	Admin hours North County / Naci	752.00	
40256546	Repair Leaks On Bolted Tank	5,266.00	
40256546	CSA 23 State Inspection	1,339.00	
40255583 40255648	Customer Account 24/25 22450 J St. replacee lid and b	410.00 149.00	0.2
40255257	CSA 23 LID Inspection - Enviro	338.00	0.19
40255236	Air Vac Maintenance	298.00	0.1
40255192	Repair water leak @ 145 S. 3rd St	2,838.00	1.2
40254926	CSA 23: Storage Tanks	21.00	0.0
40254695	Power Outage at Well #4	1,045.00	0.4
40254374	Booster Station Monthly Fuel I	50.00	0.0
40253920	Repair water leak @ 22660 I St	95.00	0.0