## CSA 23 Advisory Group Thursday, March 13, 2025 System Update

## **OPERATIONS**

- 1. System operations have been routine for the month of February.
- 2. The water status remains Normal.
- 3. Chlorine residuals average between 2.04 2.27 mg/l.
- 4. The static well depth for Well 3 is 20 feet.
- 5. The static well depth for Well 4 is 9.30 feet.
- 6. Responded to multiple Underground Service Alert (USA) location requests.

## **PROJECTS**

Welcome to Santa Margarita sign and landscaping maintenance will continue to be performed by County Public Works Utilities Staff. Lights are working great and will require minimal maintenance.

## **WATER SYSTEM PROJECTS**

Project	Description	Estimate	Phase
Replace Bolted Water Storage Tank	Replace tank to extend asset life 50 years.	\$1,750,000 This project will be funded through a grant from the American Rescue Plan Act (ARPA).	Construction contract in amount \$931,091 awarded to Crosno Construction and a Notice to Proceed has been issued for materials. Construction is expected to begin soon and be complete by the end of this year.
CSA 23 Tract 2586, Phases 1-3 (111 residential lots)	Formation of Zone A and establishment of water rates and charges within CSA 23 to provide water service to Tract 2586; Phase I (38 residential lots).	Developer funded	Preparing documents for the formation of Zone A and establishment of water rates and charges for the new Zone.  On January 16, 2025, LAFCo approved the annexation with conditions of 111 residential lots in Tract 2586 to CSA 23.

**BUDGET REPORT** 1. A budget summary is attached to this report.

Fund: Prepared by:

CSA 23 Water Monthly Report J. Cavazos 3/5/2025 2/1/25-2/28/25

Report Period: % of Yr Complete

Date of Prep:

67% **COUNTY SERVICE AREA 23 V** Internal Orders & WOs (Operations and Maint) 591R360142 CSA 23 NEW SERVICES 591R361012 CSA23 NEW SERVICES 591R36103 CSA23 TR 2586 SMRMWC 591R365135 CSA 23 WORK ORDERS 591R365150 CSA 23 GENERAL OPERATIONS 591R365181 VAC-TRON AIR 555, TRAILER MOUNTED 591R365182 MINI HYDAULIC EXCAVATOR, CAT 591R365192 MINI HYDAULIC EXCAVATOR, CAT 591R365210 CSA 23 UTILITIES 591R365310 CSA 23 WQ ANALYSES 591R365350 CSA 23 WQ OPER. SUPPORT 591R365410 CSA 23 STORMWATER ANNUAL INSPECTION 591R365602 CSA 23 ACCTG and ADMIN 591R365602 CSA 23 ACCTG and ADMIN 591R365602 CSA 23 Customer Accounts 591R365620 CSA 23 County Wide OverHead 591R360225 SCADA Efforts O&M Total O&M Capital Projects 300667 ARPA Replace Bolted Water Tank Total Capital Projects **Loan Payments** USDA Loan & Interest General Fund Loan & Interest **Total Loan Payments** GRAND TOTAL Grand Total

Bu	idget/Plan		Actual	% of	Г	Encumbered		Available
-			2.178	Budget	H	PO's	-	(2,178)
	24,910	s	38.354	154.0%				(13,444)
5	376,501	3	235,090	62.4%				141,411
	51,106		26,934	52.7%	1	100		24.172
	51,100		258	32.176				(258)
			2.764					(2.764)
	38.737		22,444	57.9%		(6)		16.293
	52.085		19,602	37.6%				32,483
	48,099		25,821	53.7%				22,278
			2,135	379634040100		19,435.20		(21,570)
	28,375		12,178	42.9%		(**		16,197
	12,742		11,077	86.9%		12		1,665
	11,112		12,283	110.5%		(*)		(1,171)
	43,315			0.0%	L	(4)		43,315
<u> </u>	686,982	\$	411,118	59.8%	\$	19,435	\$	256,429
	Budget		Actual			Encumpered PO's		Available
	1,472,794		36,058	0.0%		1,030,457		406,279
<u> </u>	1,472,794	\$	36,058		\$	1,030,457	\$	406,279
	Budget		Actual			Encumpered PO's		Available
	86,875		58,766	67.6%		-		28,109
	12,973		6,420	49.5%		7.0		6,553
;	99,848	\$	65,186	65.3%	\$	7.50	\$	34,662
			Actual		Г	Encumbered		Available
	Budget		Actual			PO's		Manuale

PO#	nnces/PO's Detail:  Vendor Name	Line on PO	Remaining Encumbered Amount	Internal Order	PO Description	Remaining Not Encumbered Available Limit	Delivery Date
25012077	ADVANTAGE TECHNICAL SERVICES INC		I	591R365135	Tank Inspection & Repair	549	6/30/2
25016435	ADVANTAGE TECHNICAL SERVICES INC line 9			591R365135			
25016758	BATTERY SYSTEMS INC			591R365135	Batteries and Supplies	8,458	6/30/2
25008913	CANNON CORP			591R365135	Blanket PO Electronic Svcs-Santa Marg	7,113	6/30/2
25017522	CROSNO CONSTRUCTION		1,024,200.00	300667.08	Contract 300667 Bolted Water Tank	-	
25017708	DC INSPECTIONS		AND ALL MANAGEMENTS	300667.08	Material Testing Tank	10,000	
25017698	GEOSOLUTIONS INC			300667.08	Material Testing Tank	10,000	
25014987	HACH CO			591R365135	NC-SD Equipment & Supplies	9,447	6/30/2
25017009	MILLER DRILLING CO			591R365135	Inspection, Labor & Replacement	10,000	
22020912	MILLER DRILLING CO		19,435.20	591R365410	Pump Replacement		
25016921	SOUZA			591R365135	CSA 23 Misc Parts and Labor	747	6/30/2
25016317	SURFACE PUMPS INC		6 Succession concepted <del>- I</del> nter	591R365150	Maintenance Services as needed	8,645	6/30/2
25004470	VICTOR BACKHOE INC			591R365135	Installations-Santa Marg	33,893	6/30/2
25016180	XIO INC	8 (Carolina)   10 Novince (Carolina)   10 Novince (Carolina)   10 Novince (Carolina)   10 Novince (Carolina)	2785×7119×23847.50-5054785	591R365135	SCADA System Equipment for CSA 23	35,000	6/30/2
25016030	YEH & ASSOC INC		6,257.10	300667.01	CSA 23 Water Storage Tanks	-	2/1/2
			1.049.892.30	[a]		133.852	

		<u>Actuals</u>	% of Total WC
40234709	Routine Operations 23/24	2,550.00	1.1
40234716	USA Locations 23/24	256.00	0.1
40234717	Weed Abatement 23/24	182.00	0.1
40234720	Customer Account 23/24	182.00	0.1
40238862	Well 3 Maintenance 23/24	298.00	0.1
40239474	Installing New Sample Station	2,221.00	0.9
40240174 40240931	Repair service leak at 22155 F Common Area Efforts	833.00 41.00	0.4
40243295	Repair service leak 22155 F St	1,111.00	0.9
40243233	Service leak repair @ 9547 Encina	2,221.00	0.9
40243443	Service line repair - 22460 F	1,388.00	0.0
40246337	North County Standby Miles	3.00	0.0
40246339	Booster Sewer Repair - Blockag	570.00	0.2
40248531	Tank Communication Issue	1,372.00	0.0
40249771	Routine Operations 24/25	104,506.00	44.
40249773	Building Maintenance 24/25	5,083.00	2.
40249774	Meter Reading 24/25	7,282.00	3.
40249775	USA Locations 24/25	4,353.00	1.
40249776	Weed Abatement 24/25	1,292.00	0.
40249777	SCADA Support 24/25	5,077.00	2.
40249780	Well #3 Filter Backwash 24/25	2,099.00	0.
40249782	Meter Replacement 24/25	1,673.00	0.
40249839	Santa Margarita Generator	128.00	0.
40250043	North County Standby Mileage	1,797.00	0.
40250046	Shared System Maintenance	1,841.00	0.
40250066	Budget Prep 24/25	1,916.00	0.
40250297	Routine Water Sample 24/25	17,175.00	7.
40250505	High Turbidity Alarm at Well #4	639.00	0.
40250696	CSA 23 Tank Communication Issue	2,105.00	0.
40250765	Lead service line inventory 24-25	13,238.00	5.
40250918	22835 El Camino Real Water Ser	617.00	0.
40250936	Annual Generator Service-Onan	875.00	0.
40251079	22909 El Camino Real Water Leak	3,807.00	1.
40251203	Late Notice Water Shut offs	298.00	0.
40251299	I Street/Estrada Service Insta	1,467.00	0.
40251361	Well #4 Low Chlorine Alarm.	2,068.00	0.
40251365	Booster Station Well Repair	86.00	0.
40251450	Install New 2" Flow Meter at W	566.00	0.
40251768	Power outage call out Well 4	182.00	0.
40251882	Gate entry camera installation	136.00	0.
40251912	Water Shut Offs CSA23	1,446.00	0.
40252025	CSA23 Distribution Maintenance	1,031.00	0.
40252335	Cycle flushing Well #3	1,539.00	0.
40252652	Low Chlorine nuisance alarm re	325.00	0.
40252981	Investigate High Chlorine leve	325.00	0.
40253643	Water Leak 22660   St.	741.00	0.
40253896	Repair water leak @ 203 Escondido	700.00	0.
40253920	Repair water leak @ 22660 I St	95.00	0.
40254374	Booster Station Monthly Fuel I	50.00	0.
40254695	Power Outage at Well #4	1,045.00	0.
40254926	CSA 23: Storage Tanks	21.00	0.
40255192	Repair water leak @ 145 S. 3rd St	2,838.00	
40255236	Air Vac Maintenance	298.00	0.
40255257	CSA 23 LID Inspection - Enviro	338.00	0.
40255583	Customer Account 24/25	410.00	0.
40255648	22450 J St. replacce lid and b	149.00	
40256546	CSA 23 State Inspection	1,339.00	
40256565	Repair Leaks On Bolted Tank	5,266.00	
40256569	Admin hours North County / Naci	752.00	
40256711	Santa Margarita Tank Daily CL2	601.00	
40256990	Valve Exercising and Hydrant M	1,446.00	
40257329	Well #4 Flushing and Cycle Test.	1,926.00	
40257330	Call Out, Possible leak By Tanks	319.00	
40257341	Innertie -	443.00	
40257372	Booster Station Monthly Fuel I	20.00	
40257461	Annual Generator Service-Onan	339.00	
40257482	9720 Encina Customer leak	941.00	
40257673	Well 4 tree trimming & limb re	3,572.00	
40258833	Well building gutter installation	1,719.00	
otal Work Orders		223,568.00	
arged Directly to IO	Office Expense US Bank	81.54	
	Souza Construction	9,255.34	
	Advantage Technical Services	1,710.00	
	OH	474.93	
		11,521.81	
Total Work Orders	I	235,090	[b]

Charged to 591R360142 New Services	
ORD 40251591 22121   St Santa Margarita	2,177.68
591R365210 CSA 23 Utilities	
ORD 40251012 Common Area Utilities FY 24/25	436.00
ORD 40240998 Office Admin Material & Cleani	20.08
ORD 40257336 Fix plugged septic line	41.00
Total	497.08
591R365410 CSA 23 STORMWATER ANNUAL INSPECTION	ON
ORD 40257480 Inspection of well #3	2,135.00
591R365602 ACCTG AND ADMIN	
ORD 40251416 Office Admin Materials & Clean	116.00